

SEP 09 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	Chevron U.S.A.	API Number	3002539097
Property Name	CDU Central Drinkard U.	Well No.	438

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
1	29	21S	37E	1235	N	790	E	LSA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	
		✓	8/28/15	INT

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				0	864
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	ok
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

No ~~Interm.~~ Surface

Signature: Saul Aranda		OIL CONSERVATION DIVISION
Printed name: Saul Aranda		Entered into RBDMS
Title: FS A		Re-test
E-mail Address: SAVW@chevron.com		
Date: 8-28-15	Phone: 575-602-1305	
	Witness:	

10/9/15

OCT 13 2015

138