State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

SEP 0 9 201

RECEIVED BRADENHEAD TEST REPORT Operator Name API Number Chevea 30-025-34905 Property Name FB DAVIS 7. Surface Location Section Township Feet from N/S Line Feet From E/W Line UL - Lot Range County 154 B 37B 510 E .06 235 350 Well Status Well Status SHUT-IN PRODUCING _ DATE 8-27-15 OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply: (B)Interm(1)-Interm(2) (A)Surf-Interm (C)Interm-Prod (D)Prod Csng (E)Tubing Pressure 0 Flow Characteristics Puff Y/N YIN Y/N Y/N YIN Steady Flow Y/N Y/N Y/N YIN Y/N Y/N Surges Y/N YIN Y/N Y / N Y/N Down to nothing Gas or Oil Y/N Y/N Y / N Water Y / N Y/N Y/N If bradenhead flowed water, check all of the descriptions that apply: FRESH CLEAR SALTY SULFUR BLACK INJECTING AT THIS TIME ____ WTR, ___ GAS, ___CO2 Remarks: 10/9/15 Signature: OIL CONSERVATION DIVISION Entered into RBDMS Printed name: Re-test E-mail Address: DUANE, KTRE OCHEVRON, COM

432. 487. 7417

Phone: Witness: