

SEP 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A	API Number 30-025-24950
Property Name ELCA	Well No. 2

7. Surface Location

UL - Lot B	Section 25	Township 22S	Range 37E	Feet from 520	N/S Line N	Feet From 1980	E/W Line E	County LJA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING ☒	DATE 8-28-15
-------------	---------	--	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				30	125
Flow Characteristics					
Puff	Y/N	Y/N	Y / N	Y / N	OK
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y/N	Y/N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Pump Unit And Pumping.

Signature: Saul Aranda 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title: FS A	Re-test
E-mail Address: SAVW@chevron.com	
Date: 8-28-15	Phone: 575-602-1305
Witness:	

BB 10/9/15

BB

OCT 1 2 2015