

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 09 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA INC.	APT Number 30-025-32217
Property Name WSST TEAS KATES SENE RIVER UNIT	Well No. WTU 941

2. Surface Location

UL - Lot A	Section 09	Township 20S	Range 33E	Feet from 330	N/S Line N	Feet From 990	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 7-16-15
-----	------------------------	-----	----------------------	------------	------------------------	-----	------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			45	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

NM NM 103145 X OLA #

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Joseph Collins	AS 10/9/15
Printed name: Joseph Collins	OIL CONSERVATION DIVISION
Title: Production Specialist Sub Surface	Entered into RBDMS
E-mail Address: Collins J @ chevron.com	Re-test
Date: 7-16-15	
Phone: 575-631-4197	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

BL