

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SOKO	API Number 30-025-00518
Property Name MAIS. UNIT	Well No. 310

2. Surface Location

UL - Lot 5	Section 12	Township 17S	Range 32E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES ☒ TA'D WELL	NO ☐	YES ☒ SHUT-IN	NO ☐	INJ ☒ INJECTOR	SWD ☐	OIL ☐ PRODUCER	GAS ☐	DATE 9/21/15
---	-----------------------------	---	-----------------------------	--	------------------------------	---------------------------------------	------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Reubin Collins	Entered into RBDMS UP
Title: Pumper	Re-test
E-mail Address: rcps90@leaco.nm	
Date: 9/21/15	
Phone:	
Witness: [Signature]	

OCT 16 2015