

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SOGO		API Number 30-025-01298	
Property Name maif. Hail		Well No. 416	

2. Surface Location

UL - Lot P	Section 7	Township 17S	Range 33E	Feet from 660	N/S Line S	Feet From 660	E/W Line E	County LCA
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS	DATE 9/22/15
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	1900
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Ø/N	Y/N	Y/N	Ø/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Reubin Collins		Entered into RBDMS	
Title: Inspector		Re-test	
E-mail Address: reubin.collins@state.nm.gov			
Date: 9/22/15	Phone: 390.8728		
Witness: [Signature]			

OCT 16 2015