

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07629
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 18

Surface Location

UL - Lot B	Section 4	Township 19-S	Range 38E	Feet from 660	N/S Line NORHT	Feet From 1980	E/W Line EAST	County LEA
---------------	--------------	------------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN <u>YES</u>	NO	INJ	INJECTOR SWD	PRODUCER <u>OIL</u>	GAS	DATE 6/25/15
------------------	----	-----------------------	----	-----	-----------------	------------------------	-----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	N/A	N/A	N/A	N/A	N/A
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / <u>N</u>	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	<u>Y</u> / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / <u>N</u>	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / <u>N</u>	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	<u>N</u> / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well Head Being Replaced

has bridge plug well bone

Kris Allen 575-631-4469

[Signature]

B8 10/15/15

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS <i>B8</i>
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: OCT - 6 2015	Phone: 806-592-6280
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 16 2015