

OCT 08 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05450
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 341

Surface Location

UL - Lot O	Section 14	Township 18-S	Range 37-E	Feet from 660	N/S Line SOUTH	Feet From 1650	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 8-17-15
--	--	--	--	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	10	—	—	410	110-115 NA
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	☒ Y ☐ N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	☒ Y ☐ N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	☒ Y ☐ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Water Flow out of Prod Casing, Steady

Did psi test on well passed

ON 8-2015 Failure

Jimi Kim

BS 10/15/15

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS <i>BS</i>
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: OCT - 6 2015	Phone: 806-592-6280
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

OCT 22 2015