

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 03 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07593
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 47

Surface Location

UL - Lot K	Section 3	Township 19S	Range 38E	Feet from 1980	N/S Line SOUTH	Feet From 1980	E/W Line WEST	County LEA
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 8-31-15
--	---	--	---	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	0	200
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Bled Tbg Down From 200 To 160. CPROX Location, Left it at 160# 10-29 called out truck bled down to & gas.
Ben Willbourn

Jenkins 575-390-0068

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS <i>BS</i>
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 10/29/2015	Phone: 806-592-6280
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

NOV 04 2015