

NOV 03 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07594
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 58

Surface Location

UL - Lot N	Section 3	Township 19S	Range 38E	Feet from 660	N/S Line SOUTH	Feet From 1980	E/W Line WEST	County LEA
---------------	--------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 8-31-15
--	---	--	---	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	50	340
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

LEFT Tbg Pressure as it was - Down town Proximity
Colled truck out (10-29) bled down & gas tanks
Dlea Dullbord

Jim King 390-0068

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 10/29/2015	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM NOV 04 2015