

SEP 09 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-06904
Property Name Central Drinkard Unit	Well No. 119

7. Surface Location

UL - Lot I	Section 30	Township 21S	Range 37E	Feet from 2160	N/S Line S	Feet From 330	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 8-31-15	INT ✓
-------------	---------	-----------	------------------------	--------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	/	/		/	830
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Joseph Collins	Entered into RBDMS B8
Title: Production Specialist Sub-Surface	Re-test
E-mail Address: CollinsJ@chevron.com	
Date: 8-31-15	Phone: 575-631-4197
Witness:	

NOV 09 2015