

NOV 20 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BC OPERATING	*API Number 30-025-39734
Property Name South Denton 6 State	Well No. 2

7. Surface Location

UL - Lot D	Section 6	Township 16S	Range 38E	Feet from 330	N/S Line N	Feet From 330	E/W Line W	County LCA
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJECTOR NO	PRODUCER SWD	GAS	DATE 4/28/15
-----	------------------------	-----	----------------------	-----------------------	------------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	2800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	BS 11/20/2015
Printed name:	OIL CONSERVATION DIVISION
Title:	Entered into RBDMS GB
E-mail Address:	Re-test
Date: 4/28/15	Witness: [Signature]

INSTRUCTIONS ON BACK OF THIS FORM

NOV 23 2015