

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MidContinent	Well Number 30 025 31462
Property Name NEST LOVINGTON UNIT	Well Test 97

* Surface Location

T1 - Lot D	Section 8	Township T17S	Range R36E	Feet from 95	NS Line N	Feet from 115	E-W Line W	County LEA
----------------------	---------------------	-------------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	----------------------

Well Status

TAD WELL ☒ YES	NO	SHUT-IN ☐ YES	NO	INJ ☐ INJ	SWD ☐ SWD	OIL ☐ OIL	GAS ☐ GAS	DATE 10/28/2015
---	----	---	----	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	---------------------------

OBSERVED DATA

	(A) Surface	(B) Intermit 1	(C) Intermit 2	(D) Prod Casing	(E) Tubing
Pressure	0				0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water flood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Eddy Gallejos	Printed name EDDY GALLEJOS
Title SSPS	Email eddy@chevron.com
Date 10/28/2015	Phone 575-441-4478

B8 11/24/15
 OIL CONSERVATION DIVISION
 District Office - RDM/MS