

NOV 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Legacy Reserve LP	*API Number 3002511480
Property Name LJU	Well No. 33

1. Surface Location

UL - Lot B	Section 6	Township 25S	Range 37E	Feet from 330	N/S Line N	Feet From 1650	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL PRODUCER OIL	GAS	DATE
------------------	----	----------------	----	-----------------	-----	---------------------	-----	------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well Plussed ✓

Signature: <i>D. Ken D. Ken</i>	11/24/15 OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS <i>BS</i>
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

NOV 30 2015