

NOV 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.	API Number 30-025-24316
Property Name Vacuum Grayburg San Andres Unit	Well No. 17

Surface Location

BL - Lot I	Section 2	Township 18S	Range 34E	Feet from 1400	N/S Line S	Feet from 10	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	------------------------	----------------------	----------------------

Well Status

TA/D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	SWD	PRODUCER OIL	GAS	DATE 5/1/15
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	1/2	2/2	0	1125
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☒
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☒
Down to nothing	0 / N	Y / N	Y / N	0 / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	158 11/24/15 OIL CONSERVATION DIVISION
Printed name: Tanner Peterson Chevron	Entered into RBDMS GB
Title: FSA	Re-test
E-mail Address: T2m@chevron.com	
Date: 5/1/15	Phone:
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

NOV 30 2015