

NOV 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name chevron, USA	API Number 3002537254
Property Name TBAU Trinity Burro ABO unit	Well No. 28

Surface Location									
UL - Lot K	Section 27	Township 12S	Range 38E	Feet from 2240	N/S Line S	Feet from 2310	E/W Line W	County LEA	

Well Status										
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 8-6-15

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Production	(E) Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Int. Casing is loose above ground, I has some play in it

Call Adriann Garcia with this

Signature: [Signature]	11/24/15
Printed name: Justin Wall	OIL CONSERVATION DIVISION [Signature]
Title: FSA	Entered into RBDMS [Signature]
E-mail Address: LSYK@chevron.com	Re-test
Date: 8-6-15	
Phone: 575 704 6224	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

NOV 30 2015