

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	API Number 3002510401
Property Name LMP5U	Well No. 523

1. Surface Location

UL - Lot M	Section 22	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet From 660	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 6/17/15
------------------	---------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			40	40
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Hold
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A gas

Signature: <i>Steve Ditty</i>	OIL CONSERVATION DIVISION
Printed name: Steven Ditty	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/22/15	
Phone:	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IN
RBDMS
gub