

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Legacy Reserves Operations LP	*API Number 3002510548
Property Name LMPVU	Well No. 301

2. Surface Location

UL - Lot A	Section 32	Township 22S	Range 37E	Feet from 330	N/S Line N	Feet From 330	E/W Line E	County Leg
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 6/17/15
------------------	---------------	-----------------	------------	-----------------	------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	30			30	30
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. Gas

Signature: <i>Steven Dittman</i>	OIL CONSERVATION DIVISION
Printed name: Steven Dittman	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/22/15	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IN
RBDMS
GMS