

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesury Reserves Operations LP	*API Number 3002510578
Property Name LMPJV	Well No. 362

1. Surface Location

UL - Lot A	Section 34	Township 22N	Range 37E	Feet from 330	N/S Line N	Feet from 990	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 6/17/15
------------------	---------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	40			40	40
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A gas

Signature: <i>Steve Dutton</i>	OIL CONSERVATION DIVISION
Printed name: Steven Dutton	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/22/15	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IP
RBDMS
DB