

DEC 01 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reservoir Operator LP	* API Number 3002534016
Property Name SP4U	Well No. 87

* Surface Location

UL - Lot 0	Section 3	Township 23S	Range 37E	Feet from 1190	N/S Line S	Feet From 1531	E/W Line E	County Leq
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR SWD	PRODUCER OIL	GAS	DATE 6/17/15
------------------	----------------	-----------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	35			35	35
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. SWS

BS 12/9/15

Signature: <i>Steve Dittmer</i>	OIL CONSERVATION DIVISION
Printed name: Steve Dittmer	Entered into RBDMS
Title: Well Tech	Re-test
E-mail Address:	
Date: 8/20/15	Phone: 432 312 4757
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IN
RBDMS
JMB