

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	API Number 3002538273
Property Name LMPJU	Well No. 601

1. Surface Location

UL - Lot 15	Section 27	Township 22S	Range 37E	Feet from 1470	N/S Line S	Feet from 2490	E/W Line W	County Lea
----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR NO	SWD NO	OIL OIL	PRODUCER GAS	DATE 6/17/15
------------------	----------------	-----------	----------------	-----------	------------	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			45	45
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A gas

Signature: <i>Steve Dittus</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test Date: 11/22/15 Phone: Witness:
Printed name: <i>Steve Dittus</i>	
Title:	
E-mail Address:	
Date: 11/22/15	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IN
RBDMS
GUB