

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	* API Number 3002538275
Property Name LMPSU	Well No. 602

Surface Location

UL - Lot G	Section 27	Township 22N	Range 37E	Feet from 2300	N/S Line N	Feet From 2275	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 6/17/15
------------------	----------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	8			55	55
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A gas

BS 12/9/15

Signature: <i>Steve Dittman</i>	OIL CONSERVATION DIVISION
Printed name: <i>Steve Dittman</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/22/15	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

IN
RBDMS
OMB