

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	*API Number 3002510558
Property Name LMP5U	Well No. 341

2. Surface Location

UL - Lot G	Section 23	Township 22S	Range 37E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	GAS	DATE 6/17/15
------------------	---------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Q	Q		50	50
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A-B gas

Signature: <i>Steve Dittman</i>	OIL CONSERVATION DIVISION
Printed name: <i>Steve Dittman</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/22/15	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

DEC 11 2015

IN
RBDMS
JAB