

DEC 01 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Pressure Operations LP	*API Number 3002510564
Property Name SP4V	Well No. 10

1 Surface Location

UL - Lot P	Section 33	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet from 330	E/W Line E	County Leq
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 6/17/15
------------------	----------------	-----------------	-----	-----	-----------------	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Cng	(E)Tubing
Pressure	0	0		0	1500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR — ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A-B Gas

BS 12/9/15

Signature: <i>Arena Dittus</i>	OIL CONSERVATION DIVISION
Printed name: Steven P. Dittus	Entered into RBDMS BS
Title: Well Tech	Re-test
E-mail Address:	
Date: 8/28/15	Phone: 432 31A 4757
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 11 2015