

DEC 01 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reservoir Operation LP	*API Number 3002510691
Property Name SPXU	Well No. 45

2. Surface Location

UL - Lot A	Section 9	Township 23S	Range 37E	Feet from 660	N/S Line N	Feet from 660	E/W Line E	County Leq
---------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	(NO)	SHUT-IN YES	(NO)	INJ	INJECTOR SWD	(OIL)	PRODUCER GAS	DATE 6/17/15
------------------	------	----------------	------	-----	-----------------	-------	-----------------	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	50			50	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. gas

BS 12/9/15

Signature: Steve Dittus	OIL CONSERVATION DIVISION
Printed name: Steve Dittus	Entered into RBDMS BS
Title: Well Tech	Re-test
E-mail Address:	
Date: 8/28/15	Phone: 432 312 4757
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 11 2015