

DEC 04 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	* API Number 3002510578
Property Name LMPDV	Well No. 362

7. Surface Location

UL - Lot A	Section 34	Township 22N	Range 37E	Feet from 330	N/S Line N	Feet from 990	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJ NO	INJECTOR SWD	PRODUCER OIL	GAS	DATE 6/17/15
------------------	---------------	-----------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	Q			40	40
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Hold
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A gas

Signature: <i>Steve Dutton</i>	OIL CONSERVATION DIVISION
Printed name: <i>Steve Dutton</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <i>11/22/15</i>	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

DEC 09 2015

DEC 11 2015