

DEC 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Seely</i>	API Number <i>30-025-01636</i>
Property Name <i>EK Penrose Sand</i>	Well No. <i>127</i>

Surface Location

UL - Lot <i>0 24</i>	Section <i>185</i>	Township <i>33E</i>	Range <i>990</i>	N/S Line <i>5</i>	Feet From <i>1980</i>	E/W Line <i>E</i>	County <i>Lea</i>
-------------------------	-----------------------	------------------------	---------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE
------------------	---------------	-----------------	-----------------	------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

will start w/o (HIT)
ASAP
[Signature]

B8 12/9/15

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS <i>GB</i>
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness: <i>[Signature]</i>	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 11 2015