

DEC 01 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lesacy Reservoir Operation LP	API Number 3002510597
Property Name SP4U	Well No. 26

* Surface Location

UL - Lot J	Section 3	Township 23S	Range 37E	Feet from 1980	N/S Line S	Feet from 1980	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 6/17/15
------------------	----------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	8	8		8	1600
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR — ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A B. gas

BS 12/9/15

Signature: <i>Steven Dittus</i>	OIL CONSERVATION DIVISION
Printed name: Steven Dittus	Entered into RBDMS <i>BS</i>
Title: Well Tech	Re-test
E-mail Address:	
Date: 8/28/15	Phone: 472 312 4757
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

DEC 11 2015