District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

A.

## State of New Mexico Energy Minerals and Natural Resources DEC 0 3 2015

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office RECEIVED

NFO Permit No.

(For Division Use Only)

## APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

whose address is \_\_\_\_7250 Dallas Parkway, Suite 1400, Plano, TX 75024

Applicant Murchison Oil & Gas, Inc.

		hereby requests an exception to Rule 19.15.1	8.12 for90 days or until March 9,	
		, Yr <u>2016</u> , for the following described tank battery (or LACT):		
		Name of Lease Brininstool 4 State 4H (30-025-41959) Name of Pool Triple X; Bone Spring		
		Location of Battery: Unit Letter M Section 4 Township 24S Range 33E		
		Number of wells producing into battery1		
В	Based upon oil production ofbarrels per day, the estimated * volume			
		of gas to be flared is100	MCF; Valueper day.	
С		Name and location of nearest gas gathering facility:		
		Frac Cat Compressor Station, Lea County, NM		
D	).	DistanceEstimated cost of connection		
Е		This exception is requested for the following reasons: <u>Intermittent curtailment by Agave due to</u> compressor maintenance. Well shut in at this time may damage formation and reduce future production.		
		compressor maintenance. Wen shut in at uns	stille may damage formation and reduce future production.	
OPERATOR			OIL CONSERVATION DIVISION	
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.			Approved Until 3/1/2016	
Signature			By Mafeys Brown	
Printed Name			Title	
& TitleGary Cooper, Vice President Operations			Title	
Email Address rcooper@jdmii.com			Date 17 9 2015	
Date 12/01/15 Telephone No. 972-931-0700				
* Gas-Oil ratio test may be required to verify estimated gas volume.				