

DEC 18 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Legacy Reserves Operating LP		API Number 3002520547
Property Name SJV South Justice Unit		Well No. 8-12

Surface Location

UL - Lot F	Section 11	Township 22S	Range 37E	Feet from 1650	N/S Line N	Feet from 2310	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 10/18/15
------------------	---------------	-----------------	-----	-----	-----------------	------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csmg	(E) Tubing
Pressure	Q			210	810
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 — WTR — GAS —
Steady Flow	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. 945
D bleed down in 2 seconds to Q

Signature: <i>Steven D. Hagan</i>		OIL CONSERVATION DIVISION	
Printed name: Steven D. Hagan		Entered into RBDMS <i>BS</i>	
Title: Well Tech		Re-test	
E-mail Address:			
Date: 12/2/15	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

DEC 21 2015