

18 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name RMR					API Number 30-025-29808				
Property Name MADALA 25 Fed					Well No. 1				
Surface Location									
UL - Lot 5	Section 26	Township 26S	Range 34E		Feet from 1980	N/S Line 5	Feet From 1980	E/W Line E	County Lea
Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ NO	INJECTOR SWD	OIL	PRODUCER	GAS	DATE 12/18/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ	N/A	N/A	880	980
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**880# on Prod. Csg Blew down to slow stream -
Shut in - Built Back up to over 750#
Immediately
- Failure -**

Signature: Robert Sanchez		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 12/18/15	Phone:		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM

DEC 31 2015

IN
[Signature]