

HOBBS OCD

DEC 18 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Legacy Reserves Operating LP	*API Number 3002531825
Property Name SJU	Well No. D-190

* Surface Location

UL - Lot A	Section 23	Township 25S	Range 37E	Feet from 200	N/S Line N	Feet from 1100	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 10/18/15
------------------	----------------	-----------------	-----	-----	-----------------	------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	0			90	530
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WIR — ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applicable

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A - gas
D. blew down to 0 in 2 seconds

Signature: <i>Steven Dittman</i>	OIL CONSERVATION DIVISION
Printed name: Steven Dittman	Entered into RBDMS BS
Title: Well Tech	Re-test
E-mail Address:	
Date: 12/2/15	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

DEC 31 2015