

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 31 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Lesacy Reserver Operations LP		*API Number 3002511322
Property Name LVL		Well No. 26

2 Surface Location

UL - Lot m	Section 32	Township 24S	Range 37E	Feet from 660	N/S Line S	Feet from 660	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 7/8/15
------------------	----	----------------	----	-----------------	-----	-----------------	-----	----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	ft 300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A-D. gas

Signature: <i>Steven D. Hae</i>	OIL CONSERVATION DIVISION	
Printed name: Steven D. Hae	Entered into RBDMS	OK
Title: Well Tech	Re-test	
E-mail Address:		
Date: 12/8/15	Phone:	
	Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JAN 05 2016