## State of New Mexico

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

JUL 1 7 2015

/		RADENHEAD TE	ST REPORT	Γ	RECEI	VED	
Operator Name					# 30-025-30090		
C1 2=	S/140 Pro	perty Name			4-	Well No.	
Cole 25 State Property Name					7/3	SWA	
		7. Surface Locat				-	
A 25	Township Range 10S 37E	Feet from 990	FNL FNL	Feet From 990	FEL.	Le	
		Well Statu	S				
Well Status	Vell Status  Down for repairs		PRODUCING		ATE 3-15		
OPEN	BRADENHEAD AND INTER	EMEDIATE TO ATMOSPH					
		OBSERVED DA					
bradenhead flowed water	er, check all of the descriptions	that apply:	IA.				
	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)	Prod Csng	(E)Tubing	
ressure	0				0	Vac	
low Characteristics						-	
Puff	Y/N	Y / N	Y/N	1	YIN		
Steady Flow	Y/N	Y / N	Y / N	1	YN	1	
Surges	Y/N	Y/N	Y/N		Y/N		
Down to nothing	Y/N	Y/N	Y / N		YIN	775	
Gas or Oil	Y/N	Y/N	Y / N		Y /(N)		
Water	Y /(N)	Y/N	Y/N	1	Y/N		
4.0							
f bradenhead flowed water	er, check all of the descriptions	that apply:					
CLEAR	FRESH	SALTY	SULFUR		BLACK		
W. / W. V.		•					
Remarks:			INJECTING AT	THIS TIME _	WTR,	GAS,C	
					BO .1.	-111	
0		1			10 110	0110	
Signature: anest Saments fr.				OIL CO	ONSERVATIO	N DI	
Printed name: Erve	est Barriente	2 dr.		Entered into	RBDMS		
Title:	To be			Re-test			
						7	
-mail Address:	_						
Date: 6-9-15	Phone:						