District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

AUG 26 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name		API Number
~~Justin Wall~~ Chevron USA Inc		3002530106
Property Name		Well No.
TBAU		21

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
N	23	12S	38E		330	S	1650	W	Lea

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	(NO)	YES	(NO)	(INJ)	SWD	OIL	GAS	8-6-15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	400		200	0
Flow Characteristics					CO2 ___ WTR ___ GAS ___ Type of Fluid Injected for Waterflood if applies
Puff	(Y) / N	Y / (N)	Y / N	Y / N	
Steady Flow	Y / (N)	(Y) / N	Y / N	Y / N	
Surges	Y / (N)	Y / (N)	Y / N	Y / N	
Down to nothing	(Y) / N	Y / (N)	Y / N	Y / N	
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / N	
Water	Y / (N)	(Y) / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Will have water Bled down By Vac truck and 24 hr test
Bled dan to zero

BS 8/26/15

Signature:	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBDMS
Title: T-SA	Re-test
E-mail Address: LJYK@Chevron.com	
Date: 8-6-15 Phone: 575 2046224	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JAN 07 2016