

HOBBS OCD

JAN 12 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	*API Number 30025 10473
Property Name LMP5V	Well No. 192

2. Surface Location

UL Lot P	Section 27	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet From 990	E/W Line E	County Lea
-------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	(NO)	SHUT-IN YES	(NO)	INJ (NO)	INJECTOR SWD	OIL PRODUCER	GAS	DATE 6/17/15
------------------	------	----------------	------	-------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	A			80	700
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applicable

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A sw
D blew down to 8 in 3 sec

Signature: <i>Steve Dittus</i>	OIL CONSERVATION DIVISION
Printed name: Steve Dittus	Entered into RBDMS <i>BL</i>
Title: Well Tech	Re-test
E-mail Address:	
Date: 11/22/15	Phone: 432 312 4757
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JAN 12 2016