



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lesacy Reserves Operations LP	*API Number 3002528461
Property Name LMPDV	Well No. 219

1. Surface Location

UL - Lot F	Section 34	Township 22S	Range 37E	Feet from 1425	N/S Line N	Feet from 1425	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 6/17/15
--	--	---	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	Q			50	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A - Gas

Signature: Steve Oltman	OIL CONSERVATION DIVISION
Printed name: Steve Oltman	Entered into RBDMS BB
Title: Well Tech	Re-test
E-mail Address:	
Date: 11/22/15	
Phone:	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JAN 12 2016