## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

David Catanach, Director Oil Conservation Division



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

14-Jan-16

CROWNQUEST OPERATING, LLC

P.O. BOX 53310 MIDLAND TX 79710

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

NEW MEXI	ICO AT STAT	TE No.001			P-10-14S-33E	30-025-01124-00-	-00	
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
01/11/2016	Routine/Periodic Violations Surface Damage/Restoration		Mark Whitaker	Yes	No	4/15/2016	iMAW1601137130	
		DO NOT RELEASE. P&A marker good. Two power poles on ground west of marker. NEED TO REMOVE POWER POLES.						

STATE FEDERAL 6 COM No.002				D-6-14S-33E	30-025-22866-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.

4/15/2016 iMAW1601139045 01/11/2016 Routine/Periodic Mark Whitaker Yes No **Violations** 

Surface Damage/Restoration

DO NOT RELEASE. Anchor southwest corner of location has not been removed. NEED TO Comments on Inspection:

REMOVE ANCHOR.

JAN 1 4 2016

## **NEW MEXICO AT STATE No.009**

M-15-14S-33E

30-025-28020-00-00

Inspection Date

Type Inspection

Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

01/11/2016 Routine/Periodic Mark Whitaker

Yes

No 4/15/2016 iMAW1601135840

**Violations** 

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE. Lease name on P&A marker not complete. Two LCEC poles (#066786 & 066787) need to be removed. Conduit protruding from ground near north pole. NEED TO CORRECT P&A MARKER. REMOVE CONDUIT. FURNISH OCD WITH A COPY OF

REQUEST TO LCEC TO REMOVE POWER POLES.

**NEW MEXICO BG STATE NCT 2** 

No.002

H-16-14S-33E

30-025-28391-00-00

Inspection

Type Inspection Date

Inspector

\*Significant Violation? Non-Compliance?

Corrective Action Due By:

Inspection No.

01/11/2016

Routine/Periodic

Mark Whitaker

No Yes

4/15/2016

iMAW1601135532

**Violations** 

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE. Conduit protruding from ground where power pole was removed. Conduit riser, fuse box, and meter base on ground. Lease name not complete on P&A marker. Should read New Mexico BG State 2 # 2, not BG 2 # 2. NEED TO REMOVE CONDUIT, FUSE BOX,

METER BASE, AND CORRECT P&A MARKER.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

oleum Engr. Specialist

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

OIL CONSERVATION DIVISION **1625 N FRENCH DRIVE HOBBS NM 88240** EMNRD

TWO WEST SECOND STREET SAMSON RESOURCES **TULSA, OK 74103**