Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010


5. Lease Serial No. NMLC031740B

NMLC031740B

Type of Well	CATE - Other instruction			8. W	73885U4940	eement, Name and/or No.
Name of Operator XTO ENERGY INCORPORATED Address 500 W ILLINOIS STREET SUITE MIDLAND, TX 79701 Location of Well (Footage, Sec., T., R.,	Contact:	STEPHANIE RAE				
3a. Address 500 W ILLINOIS STREET SUITE MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R.,	Contact:	STEPHANIE RAE		1 '	8. Well Name and No. EMSU 208	
500 W ILLINOIS STREET SUITE MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R.,		2. Name of Operator Contact: STEPHANIE RABADUE XTO ENERGY INCORPORATED				
	500 W ILLINOIS STREET SUITE 100			OCD 10.	10. Field and Pool, or Exploratory EUNICE MONUMENT	
			JAN 2 5	7016	County or Parish, EA COUNTY,	
12. CHECK APPROP	PRIATE BOX(ES) TO	INDICATE NA	TURE OF NO	TICE, REPOR	RT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans	□ Deepen□ Fracture Treat□ New Construction□ Plug and Abandon		 □ Production (Start/Resume) □ Reclamation □ Recomplete ☑ Temporarily Abandon 		☐ Water Shut-Off ☐ Well Integrity ☐ Other
Describe Proposed or Completed Operation If the proposal is to deepen directionally of	or recomplete horizontally,	give subsurface location	imated starting da	and true vertical	d work and approa	ent markers and zones.
Attach the Bond under which the work wi following completion of the involved oper testing has been completed. Final Abando determined that the site is ready for final i	rations. If the operation re- onment Notices shall be file	sults in a multiple com	pletion or recomp	letion in a new in	terval, a Form 316	0-4 shall be filed once
XTO Energy, Inc respectfully requ	ests to TA the referer	ced well with the	following proce	edure:		
1. Set CIBP @ 3630'. 2. Cap w/35' cmt via wireline or 25 3. Run good MIT.	5sxs thru tbg. WOC 4	hours. Tag.		The Control	D EOD	
A closed-loop system will be used	I to perform this opera	tion.	SEE AT	TACHE!	F APPR	OVAL

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #323226 verifie For XTO ENERGY INCORPO Committed to AFMSS for processing by LI	RATE	TED, sent to the Hobbs
Name (Printed/Typed)	STEPHANIE RABADUE	Title	itle REGULATORY ANALYST
Signature	(Electronic Submission)	Date	ate 11/11/2015
	THIS SPACE FOR FEDERA	AL OR	OR STATE OFFICE USE 1 9 2016
Approved By		Title	Title A MADATE MA
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Deffice BILLE OF CARLSBAD FIELD FIE
Title 18 U.S.C. Section 1001 States any false, fictitious	and Title 43 U.S.C. Section 1212, make it a crime for any peor fraudulent statements or representations as to any matter w	erson kno	n knowingly and willfully to make to any department or agency of the United

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 01/19/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

EMSU 208

- 1. Well is approved to be TA/SI for a period of 12 months or until 01/19/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 01/19/2017
- 4. COA's met at this time.