

HOBBS OCD

FEB 16 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED		Operator Name		API Number				
✓ Linn Operating		Property Name		36-025-11580				
✓ Langlie Matrix Queen Unit		Well No.		13				
7. Surface Location								
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
✓ D	14	25 S.	37 E	660	N	330	W	Lea
Well Status								
TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
✓ YES	NO	YES	NO	INJ	SWD	OIL	GAS	2/16/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø			Ø	460
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

M.I.T. failure, Water & pressure coming out of side of surface casing.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness:	Carol Flowers		

In

C.F.

FEB 17 2016