


District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone: (575) 393-6161 Fax: (575) 393-6720



State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA	API Number 30-025-21031
Property Name ✓ Vacuum Gloria West Unit	Well No. 126

7. Surface Location									
UL - Lot ✓ E	Section 6	Township 18S	Range 35 E	Feet from 11660	N/S Line N	Feet From 380	E/W Line W	County Lea	

Well Status									
TA'D WELL ✓ YES	<input checked="" type="radio"/> NO	YES	SHUT-IN <input checked="" type="radio"/> NO	INJECTOR INJ	SWD	PRODUCER <input checked="" type="radio"/> OIL	GAS	DATE 2/24/16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	∅			25	140
Flow Characteristics					
Puff	∅ N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	∅ / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Injected for
Water	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS CF
Title: Field Specialist	Re-test
E-mail Address:	
Date: 2-24-16	Phone: 575-513-5526
Witness: Carl Flower	

FEB 26 2016

In C.F.