

HOBBS OCD

FEB 25 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED		Operator Name		API Number	
✓		Chevron USA		30-005-35937	
✓		Property Name		Well No.	
		Trinity Burrus AB2 unit		6	
7. Surface Location					
UL - Lot	Section	Township	Range	Feet from	N/S Line
N	22	12S	38E	330	S
		Feet From	E/W Line	County	
		2310	W	Lea	
Well Status					
TA'D WELL	YES	SHUT-IN	YES	INJECTOR	DATE
	NO		NO	INJ	2/25/16
				PRODUCER	
				OIL	GAS

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	✓	✓		✓	350
Flow Characteristics					
Puff	Y / ☒	☒ Y / N	Y / N	☒ Y / N	CO2 —
Steady Flow	Y / ☒	Y / ☒	Y / N	Y / ☒	WTR ✓
Surges	Y / ☒	Y / ☒	Y / N	Y / ☒	GAS —
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒	Y / ☒	Y / N	Y / ☒	Injected for
Water	Y / ☒	Y / ☒	Y / N	Y / ☒	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Justin Wall</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Justin Wall</i>		Entered into RBDMS	
Title: <i>F-SA</i>		Re-test	
E-mail Address:			
Date: <i>2-25-16</i>	Phone: <i>706-761-0911</i>		
Witness: <i>Coral Flowers</i>			

In C.F.

MAR 01 2016