



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA	API Number 30-025-35985
Property Name Trinity Burrus ABO unit	Well No. 26

Surface Location

UL - Lot B	Section 27	Township 12S	Range 38E	Feet from 330	N/S Line N	Feet From 2000	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN NO	NO	INJECTOR INJ	SWD	OIL PRODUCER GAS	DATE 2/25/16
-------------------------	-----------	----------------------	-----------	------------------------	-----	----------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	$\emptyset$	$\emptyset$		$\emptyset$	350
Flow Characteristics					
Puff	Y / $\emptyset$	Y / N	Y / N	Y / $\emptyset$	CO2 —
Steady Flow	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	WTR ☒
Surges	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	GAS —
Down to nothing	Y / N	Y / N	Y / N	$\emptyset$ / N	Type of Fluid
Gas or Oil	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	Injected for
Water	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Justin Wall</i>	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBDMS
Title: FSA	Re-test
E-mail Address:	
Date: 2-25-16	Phone: 575 704 6224
Witness: Chae Flower	

In
C.F.

MAR 01 2016