



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA						API Number 30-025-36038			
Property Name Trinity Purus Abo Unit						Well No. 11			
Surface Location									
UL - Lot K	Section 22	Township 12 S	Range 38 E	Feet from 1650	N/S Line S	Feet From 2310	E/W Line W	County Lea	
Well Status									
YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	(INJ)	INJECTOR SWD	OIL	PRODUCER GAS	DATE 2/25/16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\emptyset$	$\emptyset$		$\emptyset$	360
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	(Y) / N	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	(Y) / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	Injected for
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: J. S. D. Wall		Entered into RBDMS	
Title: F-SA		Re-test	
E-mail Address:			
Date: 2-25-16	Phone:		
Witness: Carol Flower			

In
C.F.

MAR 01 2016