

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cross Timbers Energy, LLC	API Number 3002522001
Property Name North Vacuum ABO Unit	Well No. 119

7. Surface Location

UL - Lot F	Section 24	Township 17S	Range 34E	Feet from 2030	N/S Line FNL	Feet From 1830	E/W Line FWL	County LEA
---------------	---------------	-----------------	--------------	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

TA'D Well YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 2/23/16
--	--	--	---	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ			φ	3900
Flow Characteristics					
Puff	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	WTR. _____
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BB 3/1/16

Signature: <i>Jose Casas</i>	OIL CONSERVATION DIVISION
Printed name: Jose Casas	Entered into RBDMS <i>CB</i>
Title: lease operator	Re-test
E-mail Address: J.CASAS@ctfieldsllc.com	
Date: 2/23/16	Phone: 575-746-7220
Witness: <i>Jose Casas</i>	

In 24

MAR 01 2016