

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cross Timbers Energy, LLC	API Number 3002529236
Property Name North Vacuum ABO Unit	Well No. 279

7. Surface Location

UL - Lot E	Section 23	Township 17S	Range 34E	Feet from 2015	N/S Line FNL	Feet From 529	E/W Line FWL	County LEA
---------------	---------------	-----------------	--------------	-------------------	-----------------	------------------	-----------------	---------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER ☒ OIL GAS	DATE 2-23-16
--	--	---------------------	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	N/A	N/A	28	28
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 _____
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR. _____
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS _____
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	If applicable type
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	fluid injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 3/3/16

Signature: <i>Gene Hudson</i>	OIL CONSERVATION DIVISION
Printed name: Gene Hudson	Entered into RBDMS <i>GB</i>
Title: Pumper	Re-test
E-mail Address: <i>rhudson@ctfields.com</i>	
Date: 2-23-16	Phone: 575-441-1634
Witness:	

MAR 03 2016