

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cross Timbers Energy, LLC	* API Number 3002528936
Property Name North Vacuum ABO Unit	Well No. 270

7. Surface Location

UL - Lot O	Section 10	Township 17S	Range 34E	Feet from 540	N/S Line FSL	Feet From 1980	E/W Line FEL	County LEA
---------------	---------------	-----------------	--------------	------------------	-----------------	-------------------	-----------------	---------------

Well Status

TA'D Well YES ☒ NO ☐	SHUT-IN YES ☒ NO ☐	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 2/24/16
--	--	--	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0	N/A	N/A	30	60
Flow Characteristics					
Puff	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	CO2 _____
Steady Flow	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	WTR. _____
Surges	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	GAS _____
Down to nothing	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	If applicable type
Gas or Oil	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	fluid injected for
Water	Y / N ☒	Y / N ☐	Y / N ☐	Y / N ☐	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 3/13/16

Signature: <i>Al Lujan</i>	OIL CONSERVATION DIVISION
Printed name: <i>AL Lujan</i>	Entered into RBDMS <i>CB</i>
Title: <i>Lease Operator</i>	Re-test
E-mail Address: <i>ALlujan@ctfieldsrvcs.com</i>	
Date: <i>2/24/16</i>	Phone: <i>575-441-1638</i>
Witness: <i>[Signature]</i>	

MAR 03 2016