



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Yates Petroleum Corp</i>	API Number <i>30-025-31076</i>
Property Name <i>Flamen Co Federal</i>	Well No. <i>1</i>

7. Surface Location

UL - Lot <i>1</i>	Section <i>7</i>	Township <i>22S</i>	Range <i>32E</i>	Feet from <i>1650</i>	N/S Line <i>S</i>	Feet From <i>660</i>	E/W Line <i>W</i>	County <i>Lea</i>
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE <i>3/2/16</i>
------------------	----------------	-----------------	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>			<i>0</i>	<i>220</i>
Flow Characteristics					
Puff	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	CO2 ☐
Steady Flow	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	WTR ☒
Surges	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	GAS ☐
Down to nothing	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	Type of Fluid
Gas or Oil	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	Injected for
Water	<i>Y/N</i>	Y / N	Y / N	<i>Y/N</i>	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface Valve needs to be re-piped to surface due to breaking from corrosion.

B8 3/4/16

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>J L Olds</i>	Entered into RBDMS <i>CF</i>
Title: <i>Lease Oper.</i>	Re-test
E-mail Address: <i>513-9323</i>	
Date: <i>2/3/16</i>	Phone:
Witness: <i>Carol Flowers</i>	

In C.7.

MAR 07 2016