

HOBBS OCD

MAR 07 2016

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron, U.S.A. Inc. ✓	API Number 30-025-25815 ✓
Property Name Central Vacuum Unit ✓	Well No. 27 ✓

2. Surface Location

U.L. - Lot 5	Section 25	Township 17S	Range 34E	Feet from 1330	N/S Line S	Feet From 1425	E/W Line E	County Lea ✓
-----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	-----------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER OIL	DATE 2-18-16
------------------	---------------	----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS KH 3-8-16
Title: FSA	Re-test
E-mail Address: TZYR@Chevron.com	
Date: 2-18-16	Phone: 575-390-4449
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 08 2016