HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR 07 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron U.S.A. Inc							30-025-31784			√			
Property Name Vacuum Glorieta West Unit									1 No.	/			
		20			7. Su	rface Locatio	on						
UL - Lot	Section Z 5	Township 175	Range			Feet from Z304	N/S	Line S	Feet From	. 1	E/W Line	County Lea	1
	Well Status												
YES TA'D	WELL &	Ø YES	SHUT-IN	®	(K)	INJECTOR	SWD	OIL	PRODUCER	GAS	2.	DATE -18-16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	NA	NA	0	1225
Flow Characteristics	7	1 1/			
Puff	Y / 🕲	Y / N	Y / N	Y / 🕲	CO2
Steady Flow	Y/0	Y/N	Y / N	Y / 10	WTR X GAS
Surges	Y / 🐼	Y / N	Y / N	Y / O	Type of Fluid
Down to nothing	Ø/ N	Y/N	Y / N	Ø/ N	Injected for Waterflood if
Gas or Oil	Y /(S)	Y / N	Y / N	Y / 🕅	applies.
Water	Y/Ø	Y/N	Y / N	Y/Q	

Remarks - Please state for each string (A,B,C,D,E) pertinent info	ormation regarding bleed down or con	tinuous build up if applies.	

Signature:	7	OIL CONSERVATION DIVISION			
Printed name: Tanner DeHaan		Entered into RBDMS KH 3-8-16			
Title: FSA		Re-test			
E-mail Address: TZYR@Chevron.	.com				
Date: 2-18-16	Phone: 575-390-4449				
	Witness:				

INSTRUCTIONS ON BACK OF THIS FORM